DART SERVICE INSTRUCTION

TO AMEND INSTALLATION INSTRUCTIONS IIN-D412-698 REV. E & INSTRUCTIONS FOR CONTINUED AIRWORTHINESS ICA-D412-698 REV. 5

REF. TCCA STC SH92-43

REF. FAA STC SR01446NY REF. EASA STC EASA.IM.R.S.00709

1.0 PURPOSE

The purpose of this service instruction is to add the D412-698-111/-112 Cabin Door Roller kits for installation on aircraft equipped with cargo door assembly P/N's 205-031-669-15 (LH) and 205-031-669-16 (RH). Customers who have purchased the D412-698-011/-012 kits can upgrade to D412-698-111/-112 using the DSI 9635-011/-012 kits as follows:

- DSI 9635-011 Roller Bracket Change Kit, LH: converts a D412-698-011 to a D412-698-111;
- DSI 9635-012 Roller Bracket Change Kit, RH: converts a D412-698-012 to a D412-698-112.

2.0 PARTS LISTS

Qty	Qty	Don't Normalism	Description	
-011	-012	Part Number	Description	
X		DSI 9635-011	ROLLER BRACKET CHANGE KIT, LH (TO CONVERT A D412-698-011 KIT)	
	х	DSI 9635-012	ROLLER BRACKET CHANGE KIT, RH (TO CONVERT A D412-698-012 KIT)	
1		D3199-3	FORWARD BRACKET, LH	
	1	D3199-4	FORWARD BRACKET, RH	
1	1	D4737-041	BRACKET ASSEMBLY	
1		D4737-043	BRACKET ASSEMBLY	
	1	D4737-044	BRACKET ASSEMBLY	

Qty -111	Qty -112	Part Number	Description
Х		D412-698-111	CABIN DOOR ROLLER KIT, LH
	Х	D412-698-112	CABIN DOOR ROLLER KIT, RH
3	3	D3121-141	BRACKET ASSEMBLY
1		D3121-143	BRACKET ASSEMBLY
	1	D3121-144	BRACKET ASSEMBLY
8	8	D3199-1	BRACKET
1	,	D3199-3	FORWARD BRACKET, LH
·	1	D3199-4	FORWARD BRACKET, RH
1	1	D3202-1	COVER
1	1	D4737-041	BRACKET ASSEMBLY
1		D4737-043	BRACKET ASSEMBLY
	1	D4737-044	BRACKET ASSEMBLY

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

BY: D. SHEPHERDI(DE # 02)

DATE: _______13.01.11 CERT. NO.: ______SH92-43 ISSUE NO.: ______5

В	ADD D3199-3/-4 TO KITS			МВ	13.01.09
Α	NEW ISSU	= ,	<u> </u>	MB	12.11.21
REV.		1, 0	DESCRIPTION BY		DATE
DESIGN	DESIGN &		DART AEROSPACE LTD		
DRAWN			HAWKESBURY, ONTARIO, CANADA		ADA
CHECKED in		ip	DRAWING NO.		REV. B
MFG. APPR. N/A		N/A	DSI 9635		SHEET 1 OF 5
APPRO\	APPROVED IND		TITLE		SCALE
DE APPR.		#	ROLLER BRACKET CHANGE KIT NTS		
13.01.09			COPYRIGHT @ 2012 BY DART A THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED NOT TO BE USED FOR ANY PURPOSE OR COYED OR COMMUNICATION WRITTEN PERMISSION FROM DART ASI	ON THE EXPRE	SS CONDITION THAT IT IS




FIGURE 1 - INSTALLATION OVERVIEW

3.0 INSTALLATION

- 3.1 Remove LH and/or RH sliding doors (ref P/N 205-031-669-15/-16) from the aircraft per the Aircraft Maintenance Manual.
- 3.2 Remove 205-031-436-001 and replace with D3121-141 Bracket (3 places). Reuse existing hardware and shims if determined to be airworthy. Alternatively, if using D412-698-021 Replacement Shim Kit, install D3238-1 & D3238-11 as required. Note that the D3121-141 brackets contain one additional middle slot not used for this installation (see Figure 6 of IIN-D412-698 or Figure 52-8 of ICA-D412-698).
- 3.3 Remove 205-031-435-001/002 and replace with D3121-143 Bracket for left hand doors and D3121-144 Bracket for right hand doors. Reuse existing mounting hardware and shims if determined to be airworthy. Alternatively, if using D412-698-021 Replacement Shim Kit, install D3238-3 & D3238-13 as required. Note that the D3121-143/-144 brackets contain one additional middle slot not used for this installation (see Figure 6 of IIN-D412-698 or Figure 52-8 of ICA-D412-698).
- 3.4 Remove 205-031-433-1 Roller Support (LH) and 205-031-433-2 Roller Support (RH) and replace with D4737-043 on left hand doors and D4737-044 on right hand doors. Reuse existing mounting hardware and shims if determined to be airworthy. Alternatively, if using D412-698-021 Replacement Shim Kit, install D3238-5 & D3238-15 as required.

NOTE: The upper aft door track on early model aircraft may not have been modified to accept the extra roller on the D4737-043/-044 Brackets. If this track has not been modified, it should be modified in accordance with BHT TB 205-99-105 at this time.

DESIGN

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-O-01

APPROVED

BY:
D. SHEPHER® (DE # 02)

DATE:
13.01.11
CERT. NO.:
SH92-43
ISSUE NO.:
5

DRAWN		HAWKESBURY, ONTARIO, CAN	AUA
CHECKED	ip	DRAWING NO.	REV. B
MFG. APPR.	N/A	DSI 9635	SHEET 2 OF 5
APPROVED	, MAP,	TITLE	SCALE
DE APPR.	#	ROLLER BRACKET CHANGE KIT	NTS
DATE 13.0	1.09	COPYRIGHT @ 2012 BY DART AEROSPACE THIS COCUMENT IS PRIVATE AND CONFIDENTIA, AND IS SUPPLIED ON THE EXPRES NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMANINCATE TO ANY OT WRITTEN PERMISSION FROM DART AEROSPACE LTD.	SS CONDITION THAT IT IS

DART AEROSPACE I

- 3.5 Remove 205-031-434-1 Roller Support and replace with D4737-041. Reuse existing mounting hardware and shims if determined to be airworthy. Alternatively, if using D412-698-021 Replacement Shim Kit, install D3238-5 & D3238-15 as required.
- 3.6 Remove 205-032-669-125 Track (LH) and/or 205-032-669-126 Track (RH) as applicable. Install D3199-1/-3/-4 Brackets and D3202-1 Cover as shown in Figure 2 using existing mounting hardware if determined to be airworthy.
- 3.7 Re-install LH and/or RH doors on the aircraft per the Aircraft Maintenance Manual. Check sliding operation of door. Adjust position/shimming of all new brackets until door operation is smooth and free of dragging/binding through full travel of the door. Once the door is sliding smoothly, torque all fasteners per Aircraft Maintenance Manual.
 NOTE: To prevent roller wear and premature door track wear, ensure vertical rollers are sitting flush to door tracks.
- 3.8 NOTE: It is acceptable to install any portion of the D412-698-111/-112 kits in combination with the existing Bell door components. Replacement parts may be ordered individually as follows:

Bell Part Number	Location	Dart Replacement Part Number	Applicable Instruction
205-031-436-001	STA 162 in STA 140 in STA 116 in	D3121-141	3.2
205-031-435-001	STA 96 in	D3121-143	3.3
205-031-435-002	STA 96 in	D3121-144	3.3
205-031-433-1	STA 168 in	D4737-043	3.4
205-031-433-2	STA 168 in	D4737-044	3.4
205-031-434-1	STA 168 in	D4737-041	3.5

4.0 WEIGHT AND BALANCE


		LAT	ERAL	LON	GITUDINAL
INSTALLATION	WEIGHT	Arm	Moment	Arm	Moment
D412-698-111 Cabin Door	0.98 lb	-48.0 in	-47.0 in lb	130 in	127.4 in lb
Roller Kits (net)	0.44 kg	-1.22 m	-0.54 m kg	3.30 m	1.45 m kg
D412-698-112 Cabin Door	0.98 lb	48.0 in	47.0 in lb	130 in	127.4 in lb
Roller Kits (net)	0.44 kg	1.22 m	0.54 m kg	3.30 m	1.45 m kg
Both D412-698-111/-112	1.96 lb	0 in	0 in lb	130 in	254,8 in lb
Installed (net)	0.88 kg	0 m	0 m kg	3.30 m	2.90 m kg
Replace 205-031-433-1 with	0.19 lb	-48.0 in	-9.1 in lb	168 in	31.9 in lb
D4737-043 (net)	0.09 kg	-1.22 m	-0.11 m kg	4.27 m	0.38 m kg
Replace 205-031-433-2 with	0.19 lb	48.0 in	9.1 in lb	168 in	31.9 in lb
D4737-044 (net)	0.09 kg	1.22 m	0.11 m kg	4.27 m	0.38 m kg
Replace 205-031-434-1 with	0.12 lb	+/-48.0 in	+/-5.8 in lb	168 in	20.2 in lb
D4737-041 (net)	0.05 kg	+/-1.22 m	+/-0.06 m kg	4.27 m	0.21 m kg

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-0-01


BY: D. SHEPHER (DE # 02)

DATE: 13.01.11
CERT. NO.: SH92-43
ISSUE NO.: 5

DESIGN		DART AEROSPACE	LTD
DRAWN		HAWKESBURY, ONTARIO, CAN	
CHECKED	SP	DRAWING NO.	REV. B
MFG. APPR.	N/A	DSI 9635	SHEET 3 OF 5
APPROVED	TWP.	TITLE	SCALE
DE APPR.	#	ROLLER BRACKET CHANGE KIT	NTS
DATE 13.0	1.09	COPYRIGHT © 2012 BY DART AEROSPAC THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRI NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY	EBB CONDITION THAT IT IS



OUTSIDE VIEW OF LH SLIDING DOOR (LOOKING INBOARD)
(RH DOOR OPPOSITE)



INSIDE VIEW OF LH SLIDING DOOR (LOOKING OUTBOARD) (RH DOOR OPPOSITE)

FIGURE 2 - MODIFIED SLIDING DOOR

(D412-698-111 SHOWN, D412-698-112 OPPOSITE)

CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-0-01

APPROVED

BY:
D. SHEPHERD (DE # 02)

DATE:
13.01.11
CERT. NO.:
SH92-43
ISSUE NO.:
5


DESIGN	15	DART AEROSPACE	LTD
DRAWN	13	HAWKESBURY, ONTARIO, CAN	IADA
CHECKED	W	DRAWING NO.	REV. B
MFG. APPR.	N/A	DSI 9635	SHEET 4 OF 5
APPROVED	W	TITLE	SCALE
DE APPR.	-#	ROLLER BRACKET CHANGE KIT	NTS
DATE 13.0	1.09	COPYRIGHT @ 2012 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WINTEN PERMISSION FROM DART AEROSPACE LTD.	

5.0 MAINTENANCE

Maintain D412-698-111/-112 in accordance with ICA-D412-698 for the D412-698-011/-012 Kits.


6.0 D4737-041/-043/-044 REPLACEMENT PARTS

For D3121-141/-143/-144 Bracket Assemblies, see Section 5.0 of IIN-D412-698 (Section 52.14 of ICA-D412-698).



D4737-041 BRACKET ASSEMBLY

D4737-043/-044 BRACKET ASSEMBLY



CANADA
DEPARTMENT OF TRANSPORT
AIRCRAFT CERTIFICATION
BRANCH
DAO # 01-0-01

APPROVED

BY: D. SHEPHERD (DE # 02)

DATE: 13.01.11
CERT. NO.: SH92-43
ISSUE NO.: 5

DESIGN		DART AEROSPAC	E LTD
DRAWN	13	HAWKESBURY, ONTARIO, C	ANADA
CHECKED	UP	DRAWING NO.	REV. B
MFG. APPR.	N/A	DSI 9635	SHEET 5 OF 5
APPROVED	cup.	TITLE	SCALE
DE APPR.		ROLLER BRACKET CHANGE K	IT NTS
DATE 13.0	1.09	COPYRIGHT © 2012 BY DART AEROSP THIS DOCUMENT IS PRIVATE AND DOMINISHMAL AND IS SUPPLIED ON THE E NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO A WRITTEN PERMISSION FROM DART AEROSPACE	XPRESS CONDITION THAT IT IS MY OTHER PERSON WITHOUT